Exhibit 1

12328	CN	2/27/90	Report		100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	4/10/92	Report	Decodatos - Project Pabba - Lab	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	8/22/94		Bulk sample analysis by Pinchin Environmental - Project 5670 - Lab Reference # b7188-1994	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	10/24/94	Report	Bulk sample analysis by Pinchin Environmental - Project 5670 - Lab Reference # b7393-1994	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	5/27/03	Report	Bulk sample analysis by Pinchin Environmental - Project 22092 - Lab Reference # b24483-2003	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	5/30/03	Report	Bulk sample analysis by Pinchin Environmental - Project 22092 - Lab Reference # b24520-2003	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	9/16/03	Letter/Report	Letter/Report from Pinchin Environmental to Ryerson University re: Kerr Hall - Room W177 - Air Monitoring - Pinchin Project No. 23285	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	4/00/91	Report	Asbestos Removal - Lower Gymnasium and Theatre Arts Workshop - Ryerson Polytechnical Institute - Pinchin Project No. 2771	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	Undated	Report	Asbestos Removal - Project No. 2771 - Instructions to Bidders	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	9/7/94	Change Request	Proposed changes by Pinchin & Associates to abatement project at Ryerson Polytechnical University re: Alterations to 3rd Floor, South Kerr Hall	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	Undated	Chart (attached to claim form)	Ryerson Polytechnic University Building List - proof of age	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	9/7/94	Report	Pinchin Environmental Procudres for Type 2 Mech. & Elec. Work - Ryerson University - Alterations to 3rd Floor South Kerr Hall	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	9/7/94	Report	Pinchin Environmental Scope of Work - Type 2 Asbestos Abatement Contractor - Ryerson University - Alterations to 3rd Floor South Kerr Hall		Speights & Runyan
12328	CN	7/00/03	Report	Hazardous Building Materials Report for Kerr Hall, Ryerson University	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	Undated	Chart	List of buildings with age, square feet	100 Oak Street Hampton, SC	Speights & Runyan

12328	CN	10/2/89	Letter	Puercon regional containment	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	10/18/89	Letter	Letter from Pinchin & Associates to Ryerson summarizing tenders to Ceiling Containment Project - Upper Gymnasium - Kerr Hall	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	4/25/91	Report	Addendum No. 1 by Pinchin & Associates to contract documents re: asbestos removal - Ryerson - Lower Gym and Theatre Arts Workshop	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	5/2/91	Minutes	Minutes of Meeting No. 1 at Ryerson Polytechnical Institute re: Asbestos Removal - Lower Gym and Theatre Arts Workshop	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	6/14/91	Letter	Letter from Pinchin & Associates to Biggs and Narcisco Construction re: Asbestos Removal - Gym and Theatre Arts Workshop - Project # 2772	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	7/2/91	Letter	Letter from Pinchin & Associates to Ryerson Polytechnical re: Asbestos Removal - Kerr Hall Lower Gym and Theatre Arts Workshop - Project # 2772	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	7/22/91	Letter	Letter from Pinchin & Associates to Ryerson Polytechnical re: Roof Repairs - Kerr Hall - Project # 2554	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	5/4/92	Letter	Letter from Pinchin & Associates to Ryerson Polytechnical re: Dust Sampling - Howard Kerr Hall - Room E132 - Project # 2554	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	5/5/92	Letter	Letter from Pinchin & Associates to Ryerson Polytechnical re: Asbestos Inspection - Howard Kerr Hall - Room N-4 - Project # 2554	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	5/2/94	Letter	Letter from Pinchin Environmental to Ryerson Polytechnical re: Asbestos Removal - Various Areas - Howard Kerr Hall	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	6/22/94	Letter	Letter from Pinchin Envrironmental to Ryerson Polytechnical re: Asbestos Removal Third Floor - South Kerr Hall	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	6/22/94	Letter	Letter from Pinchin Environmental to Ryerson Polytechnical re: Asbestos Removal - Various Areas - Howard Kerr Hall	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	10/21/94	Letter	Letter from Pinchin Environmental to Ryerson Polytechnical re: Asbestos Removal - N107 & N107a - Howard Kerr Hall	100 Oak Street Hampton, SC	Speights & Runyan

1				1	ı	1 1
12328	CN	1/31/01	Letter/Report	Letter/Report from Pinchin Environmental to Ryerson University re: Budget Fees for Asbestos Consulting Services Ryerson University Campus - Pinchin Project R15416	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	5/8/03	Letter	Leter from Pinchin Environmental to Kongats Architects re: Fee Proposal for Consulting Services at Kerr Hall Ryerson - File No. 22092	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	5/28/03	Letter	Letter from Pinchin Environmental to Ryerson University re: Letter of Findings - Kerr Hall, Ryerson University - Room W-177A - Pinchin File 22092	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	6/3/03	Letter	Letter from Pinchin Environmental to Ryerson University re: Letter of Findings - Kerr Hall, Ryerson University - Room W-177A - Pinchin File 22092	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	6/4/03	Memo	Memo from Tim Lee of Kongats Architects to Jule Mycan re: Ryerson University - Kerr Hall - W-177 Classroom/Existing Server Room	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	6/17/03	Letter	Letter from Pinchin Environmental to Ryerson University re: Letter of Findings - Kerr Hall, Ryerson University - Room W-177A REVISED- Pinchin File 22092	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	6/00/03	Drawings	Floor Plans - Ryerson Kerr Hall, Toronto, Ontario	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	6/28/90	Invoice	Invoice from Pinchin & Associates to Ryerson re: Kerr Hall Mechanical Room \$645.00 consulting, inspection and air monitoring services	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	12/10/90	Invoice	Invoice from Pinchin & Associates to Ryerson re: Room 277, inspection and air monitoring services - \$1,054.60	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	11/26/90	Invoice	Invoice from Pinchin & Associates to Ryerson re: Asbsetos Removal, Room 277, etc \$4,040.85	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	2/28/91	Invoice	Invoice from Pinchin & Associates to Ryerson re: Kerr Hall , Texture Coat Removal - \$749.00	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	5/30/91	Invoice	Invoice from Pinchin & Associates to Ryerson re: Asbestos Removal - Kerr Hall - Lower Gym & Theatre Arts Workshop - \$4,750.80	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	6/30/91	Invoice	Invoice from Pinchin & Associates to Ryerson re: Kerr Hall, Texture Coat Removal - \$417.30	100 Oak Street Hampton, SC	Speights & Runyan

Case 01-01139-AMC Doc 10496-1 Filed 10/23/05 Page 5 of 5

12328	CN	6/30/91	Invoice	1	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	8/30/91	Invoice	Invoice from Pinchin & Associates to Ryerson re: Asbestos Removal - Gym & Theatre Arts - Kerr Hall - \$1,540.80	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	8/30/91	Invoice	Invoice from Pinchin & Associates to Ryerson re: Kerr Hall, Texture Coat Removal - \$2,109.09	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	5/29/92	Invoice	Invoice from Pinchin & Associates to Ryerson re: Howard Kerr Hall, Room E-132 and Room N-4 - inspection & consulting services - \$838.77	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	7/29/94	Invoice	Invoice from Pinchin Environmental to Ryerson re: Consulting & Inspections, Howard Kerr Hall - \$2,573.34	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	9/30/94	Invoice	Invoice from Pinchin Environmental to Ryerson re: Asbestos Inspection at Kerr Hall - \$2,052.14	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	10/31/94	Invoice	Invoice from Pinchin Environmental to Ryerson re: Asbestos Inspection at Kerr Hall - \$3,060.62	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	11/28/94	Invoice	Invoice from Pinchin Environmental to Ryerson re: Asbesetos Inspection - \$608.39	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	9/12/03	Invoice	Invoice from Pinchin Environmental to Ryerson re: Consulting Services, Asbestos Survey and Specifications at Kerr Hall - \$3,197.16	100 Oak Street Hampton, SC	Speights & Runyan
12328	CN	11/24/03	Invoice	Invoice from Pinchin Environmental to Ryerson re: Air Sampling and Analysis, Kerr Hall - \$433.70	100 Oak Street Hampton, SC	Speights & Runyan